



Tak Cheong Industrial Zone, Bubian, Shanwei Guangdong, PRC.

产品中止公告

PDN 编号: PDN-09-001

分布日期: 2009-04-30

主题: 停止生产SOD123 & SOD323 Clip Bond产品

最后购买日期: 2009年5月份之前

最后发货日期: 2009年5月份之前

若你对此通知有任何疑问, 请联系

姓名 : Engelbert Lo
邮件地址 : engelbert.lo@takcheong.com
联系电话 : 86-660-337 5888 ext. 8042
直线 : 86-660-337 6121

通知类型:

产品停止生产, 并将自发布日期起的30天内生效。

描述与目的:

根据工厂制造能力, 德昌决定停止SOD123 & SOD323 Clip Bond产品的生产, 并使用SOD123 & SOD323 Wire Bond产品代替SOD123 & SOD323 Clip Bond产品.

受影响产品清单: 所有 SOD123 & SOD323 Clip Bond 产品

可能代替的产品: Wire Bond 产品

批准人:

Manufacturing Manager:

QA Service Manager:

Manufacturing QA Manager:

Business Development Manager:

.....



Tak Cheong Industrial Zone, Bubian, Shanwei Guangdong, PRC.

PRODUCT DISCONTINUE NOTIFICATION

PDN No: PDN-09-001

RELEASE DATE: 2009-04-30

AFFECTED DEVICE LIST:

From <u>SOD323 Clip Bond</u>	To <u>SOD323 Wire Bond</u>	From <u>SOD123 Clip Bond</u>	To <u>SOD123 Wire Bond</u>
TC1N4148WS	1N4148WS	TC1N4148W	1N4148W
TC1N4448WS	1N4448WS	TC1N4448W	1N4448W
TC1N914BWS	1N914BWS	TC1N914BW	1N914BW
TC1SS355	1SS355	TCBAV19W	BAV19W
TCBAV19WS	BAV19WS	TCBAV20W	BAV20W
TCBAV20WS	BAV20WS	TCBAV21W	BAV21W
TCBAV21WS	BAV21WS	TCMMSZ2V4 Through TCMMSZ75V	MMSZ2V4CW through MMSZ75VCW
TCBAT42WS	BAT42WS	TCMMSZ2V4B Through TCMMSZ75VB	MMSZ2V4BW through MMSZ75VBW
TCBAT43WS	BAT43WS	TCMMSZ5221B Through TCMMSZ5263B	MMSZ5221BW through MMSZ5263BW
TCRB551V-30	RB551V-30		
TCRB501V-40	RB501V-40		
RB751V-40	RB751V-40		
BAT54WS	BAT54WS		
TC2V4B Through TC75VB TCMM3Z2V4B Through TCMM3Z75VB	MM3Z2V4BW Through MM3Z75VBW		
TC2V4C Through TC75VC TCMM3Z2V0C Through TCMM3Z75VC	MM3Z2V4CW Through MM3Z75VCW		
TCUDZS2V0B Through TCUDZS36VB TCZS2V0B Through TCZS36VB	UDZS2V0BW Through UDZS36VBW		
MMSZ5221BS Through MMSZ5263BS	MMSZ5221BSW Through MMSZ5263BSW		
TCMAZ2V0 Through TCMAZ39V	---		